

**NATIONAL RADIO ASTRONOMY OBSERVATORY**  
Socorro, New Mexico

VLBA Antenna Memo Series No.24

**St. Croix Maintenance Visit, January 15 - 20, 2000 - Trip Report**

J. E. Thunborg  
January 30, 2000

**Attachments: Wheel Worksheet, Gain Curves**

During the St. Croix maintenance visit in June 1999, the Azimuth #1 Drive wheel was popping and had pitted races in both bearings. A maintenance team consisting of T. Frost, R. Gutierrez, R. Molina, J. Rodriguez, P. Sanchez and J. Thunborg was dispatched to St. Croix to change the wheel. The wheel change, along with several other tasks, was accomplished. The site techs J. Williams and H. Winchel also worked toward the completion of the scheduled tasks.

A new wheel assembly with a heat-treated 4340 steel axle (Drawing D52502MO25, Revision D) was installed on the antenna. After the wheel was aligned the antenna was used for 2 days and then the alignment was re-measured. Below are the results from this final measurement.

	<b>Measured</b>	<b>Specified</b>
Conic radius	300.121"	300" $\pm$ 1/4"
Coupling	0.001" TIR	Not Specified
Axle Vertical Slope	93° 27' 05"	93° 26' 23" $\pm$ 1.4'
Axle Horizontal error	10"	< 1.4'


Servo tests indicated that the new wheel assembly had no measurable impact on servo performance.

Several other tasks accomplished by the maintenance team are listed below.


1. The FRM subreflector was moved. Repositioning the subreflector improved the antenna performance somewhat but it has still not recovered to its pre 1995 status. See attached for plots generated by Vivek Dhawan. Current theory is that there may something loose in the FRM. This will be checked using digital dial indicators on the next visit to St. Croix.
2. A rusted stair tread was replaced.
3. Several rusted feed bolts were replaced
4. An elevation counterweight measurement was performed indicating that the telescope is currently 60,000 ft-lbs dish heavy.
5. The FRM hardstops were replaced with chemical resistant ones. The hard stops that were replaced during the July Tiger Team were already showing signs of softening.
6. The FRM cable track was replaced with Gore track.
7. The FRM cables and J boxes were replaced with new ones. The original J-boxes were almost completely rusted through.

8. The rusted angle brackets that hold the gearbox flow indicators were replaced with brackets made from stainless steel.
9. The guy rod cotter keys were replaced.
10. The FRM second screw sensor was replaced.
11. The FRM turnbuckles were replaced with rust resistant brass.
12. A crack in the diesel generator radiator was soldered.
13. Installed guard rail at the antenna apex (see change order #119)
14. The FRM torque requirement was measured. The FRM required 17 lbs of force at the barrel to rotate.
15. A small platform was installed to facilitate installation of the stow pin.
16. The servo motor J-boxes were replaced with stainless steel ones.

The 6 by 10-inch gash shown below was found on the edge of the subreflector. Bondo was used to repair the Subreflector. However, a reflective surface was not installed over the Bondo. The systems engineers who understand these sorts of things should consider the effect of this repair on antenna performance. The cause of the gash is not currently known.



Before



After

A visual inspection of the paint on the antenna showed that the painters are beginning to get ahead of the corrosion. The painters have been concentrating on the backup structure and the major structural members. These areas showed very little rust. However, additional painting is needed on the secondary parts of the structure. We should continue painting the antenna during maintenance periods with emphasis placed on the most severely rusted areas like the undersides of the elevation platforms.

# WHEEL ALIGNMENT (Antenna Center Calculation)

## Equal distance method

**Procedure:** Set up theodolite 3 to 5 feet away from axle. Rotate antenna until the measurement point is 100 inches from theodolite and record ACU and theodolite(az and el) readings. Rotate in opposite direction until measuring point is 100 inches on other side of theodolite. Record ACU and Theodolite readings. Measure and record distance from wheel center to measurement point.

**Worksheet:**

Wheel # 1 AZ DRIVE, HOT TREATED AXLE

Set distance (d) 200

Theo1 Elevation 91.3450

Theo1 el degrees

91.58

Theo1 Azimuth 0, 0, 16

Theo1 az degrees

.00444

Theo2 Azimuth 85.0208

Theo2 az degrees

85.0355

ACU1 Azimuth 92.7675

Theodolite difference

85.0311

ACU2 Azimuth 41.775

ACU difference

50.9925

Offset 13.75

R

Radius

300.121

ACU\_center

67.271

### EXAMPLE

$d := 100\text{-in}$

Distance from Theodolite to measuring point (~100 inches)

$Theo\_el := 92.6599\text{-deg}$

Elevation angle of theodolite (either side)

$Theo1 := 100\text{-deg}$

First Theodolite Reading

$Theo2 := 196.2289\text{-deg}$

Second Theodolite Reading

$ACU1 := 180\text{-deg}$

First ACU Reading

$ACU2 := 207.1904\text{-deg}$

Second ACU Reading

$Offset := 16.375\text{-in}$

Distance from measuring point to wheel center

$Theo\_hor := Theo2 - Theo1$

$Theo\_hor = 96.229\text{-deg}$

$ACU := ACU2 - ACU1$

$ACU = 27.19\text{-deg}$

$R := d \cdot \sin(Theo\_el) \cdot \frac{\sin(\frac{ACU}{2})}{\sin(\frac{Theo\_hor}{2})}$

$R = 316.377\text{-in}$

$.43045$

Horizontal

~~42 30 50~~  
~~42 31 12~~  
42 31 12

Horizontal

$Radius := R - Offset$

$Radius = 300.002\text{-in}$

$ACU\_center := ACU1 - \frac{ACU}{2}$

$ACU\_center = 166.405\text{-deg}$

269  
266  
3

59 60  
32 10  
27 50

Vertical


flip

AVG

42 31 12 center  
42 31 02 meas  
ERROR 10"  
93 26 2:  
93 26 2:  
3 27 50  
3 27 05  
AVG 3 27 02



SC

7mm, 2000 jan21-28



SC. 2000, Jan 19

Orion 7mm





SC

20 Jan '00

orion

7mm



6300 counts

$\phi = 55^\circ$

UT, 20 Jan