VLBA ACQUISITION MEMO #243

MASSACHUSETTS INSTITUTE OF TECHNOLOGY HAYSTACK OBSERVATORY

14 February 1991

TO: VLBA Data Acquisition Group

FROM : Dan Smythe

SUBJECT : Capacitance of Gapped Bars

Since the glass in the gap is silicon dioxide, an insulator with a known dielectric constant, it is possible to measure the gap length by measuring the capacitance across the gap. To this end, two gapped bars were measured at a frequencies between 10 and 500 KHz. Since the resistivity of the ferrite is fairly high and would introduce a series resistance that would dominate the capacitance measurement, small wires were bonded to the edges of the bar with conductive paint, which can be washed off with acetone. I found that the gaps were shunted with a DC resistance as low as 720 ohms, a shunt probably caused by ferrite in the gap, or smeared across the surface of the gap.

The results of some of these measurements are shown in the table, where a dielectric constant of 4 has been used to calculate the gap length from the measured capacitance. A frequency of 100 KHz was chosen to ensure that the capacitive reactance is less than the shunt resistance, and still much greater than the series resistance of a few ohms. In fact, the capacitance changes by less than 10 percent between 10 and 400 Khz.

| | DC | 100 KHz | | |
|-----|------------|------------|-------------|------------|
| Bar | Resistance | Resistance | Capacitance | Gap Length |
| | ohms | ohms | nf | μ m |
| 1 | 4750 | 3460 | 4.580 | .200 |
| 2 | 720 | 662 | 4.683 | .196 |

The uncertainty in the calculation of gap length is about 8 percent, or $\pm 0.016\mu$ m, primarily because of uncertainty in the gap area within the mechanical tolerances of the bar. This gap length agrees with preliminary scanning electron microscope measurements, but disagrees with the .25 μ m calculated from the gap null in VLBA Acquisition Memo #184. This difference between the mechanical and magnetic gap length could be the result of a dead layer in the ferrite of 0.025 μ m on each side of the gap, and is consistent with the 0.05 μ m dead layer reported in VLBA Acquisition Memo #207. If there is such a dead layer, we should be careful about changing the method of measuring the gap length, since head performance is determined by the effective magnetic gap length.