National Radio Astronomy Observatory Tucson, Arizona

March 30, 1988

MEMORANDUM

To: John Payne

From: P. R. Jewell

Subject: A possible problem with the focus drive/readout

I have attached 3 focus curves taken yesterday at 345 GHz. Note that 2 of the curves have notches in them, but the other is smooth. The data were taken under perfectly clear skies and both receiver channels have the same appearance. I have seen this problem before and it suggests that we may have a problem in the focus drive or readout system.

Distribution:

- D. Emerson
- R. Freund
- J. Lamb
 - A. Perfetto





